



Ridge Tool Company  
400 Clark St.  
Elyria, OH 44035-6001  
USA


T (440) 323 5581

## IMPORTANT SAFETY NOTICE

**SUBJECT: All RIDGID® Micro CG-100 Combustible Gas Sniffers (Catalog #26148)  
Produced before February, 2008:**



Micro CG-100 Combustible Gas Sniffer



Rev. 2

Correct Operating Decal On Back of Gas Sniffer



March 3, 2008

**This is a Product Retrofit Notice.** Ridge Tool recently determined that the on-product operating decal and user manual included with these Gas Sniffers are incorrect. As a result, a user would think they are detecting combustible gases down to concentrations of 40 parts per million (ppm), when in fact they are only detecting combustible gas concentrations down to 400 ppm. **This could lead to combustible gas concentrations of less than 400 ppm not being detected.**

**All RIDGID Micro CG-100 Combustible Gas Sniffers (Catalog #26148) produced before February, 2008 are affected by this issue.** Affected Gas Sniffers can be identified by looking at the operating decal on the back of the unit and the user manual. If the decal and user manual are not marked with "Rev. 2" or "Revision 2" higher (see above photos), they are not correct and need to be retrofitted. Any Gas Sniffer produced after February 2008 has the correct decal and manual and is not subject to this safety notice.

Please take immediate steps to determine if you have any of these products in your possession. Do not use affected Gas Sniffers until they have been retrofitted. Contact Ridge Tool Technical Services at (800) 519-3456 or [TechServices@ridgid.com](mailto:TechServices@ridgid.com). Ridge Tool will provide parts and information to retrofit the Gas Sniffer with the correct decal and manual.

Thank you for your cooperation and we regret any inconvenience that this may have caused you. If you have any questions, please contact Ridge Tool Technical Services at (800) 519-3456 or [TechServices@ridgid.com](mailto:TechServices@ridgid.com).

